
BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

ABB Touch DCA

BJE Touch DCA

[English](#)

[Deutsch](#)

ABB STOTZ-KONTAKT GmbH
Eppelheimer Straße 82
69123 Heidelberg, Germany
Telefon: +49 (0)6221 701 607
Telefax: +49 (0)6221 701 724
E-Mail: info.bje@de.abb.com
www.abb.com/knx

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

ABB Touch DCA

BJE Touch DCA

Product name	ABB RoomTouch® 5", 30-fold, FM Busch-RoomTouch® 5", 30-fold, FM Busch-SmartTouch® 7", 480-fold, FM IP touch 7. LAN / WLAN, FM IP touch 7. LAN / LAN, FM IP touch 10. LAN / WLAN, FM IP touch 10. LAN / LAN, FM
Product type	RT/U30.0.1(1)-8xx 6136/07-8xx(-500) H8236x-x-03 H8236-xxx H8236-xx-03 H8237-xx-03 H8237-xxx
Order code	2TMA200050W0007, 2TMA200050B0005 2TMA200050W0010, 2TMA200050B0008 2CKA006136A0203, 2CKA006136A0204 2CKA006136A0205, 2CKA006136A0206 2TMA130051W0004, 2TMA130051B0004, 2TMA130051W0005, 2TMA130051B0005, 2TMA130051W0002, 2TMA130051B0002, 2TMA130051W0003, 2TMA130051B0003, 2TMA130050W0054, 2TMA130050B0054, 2TMA130050W0055, 2TMA130050B0055 2TMA130050W0058, 2TMA130050B0058, 2TMA130050W0060, 2TMA130050B0060 2TMA130050W0063, 2TMA130050B0063, 2TMA130050W0064, 2TMA130050B0064, 2TMA130051W0006, 2TMA130051B0006, 2TMA130051W0007, 2TMA130051B0007, 2TMA130050W0065, 2TMA130050B0065, 2TMA130050W0067, 2TMA130050B0067 2TMA130050W0066, 2TMA130050B0066, 2TMA130050W0068, 2TMA130050B0068 2TMA130050B0066, 2TMA130050W0066, 2TMA130050B0068, 2TMA130050W0068
Latest change	28/05/2021 DCA repair button

Current Status:

DCA
ABB Touch DCA Download
BJE Touch DCA Download

NOTE:

We recommend to ensure that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up-to-date will to be accepted.

DEVICE CONFIGURATION APP

Version	Since	Updates and Release Notes
1.1.16.0	05/2021	Extended the things that can be repaired when activating the repair button
1.1.14.0	04/2021	New repair button and bugfixes
1.1.10.0	02/2021	Bugfix in this automatic troubleshooting process
1.1.7.0	02/2021	Automatic troubleshooting for copying or deleting problems
1.1.1 (Build 4)	11/2020	Added the IP Touch panels
1.1.1 (Build 1)	09/2020	Market introduction

HAUS- UND GEBÄUDEAUTOMATION

Softwareinformation

ABB Touch DCA

BJE Touch DCA

Produktname	ABB RoomTouch® 5", 30-fold, FM Busch-RoomTouch® 5", 30-fold, FM Busch-SmartTouch® 7", 480-fold, FM IP touch 7. LAN / WLAN, FM IP touch 7. LAN / LAN, FM IP touch 10. LAN / WLAN, FM IP touch 10. LAN / LAN, FM
Produkttyp	RT/U30.0.1(1)-8xx 6136/07-8xx(-500) H8236x-x-03 H8236-xxx H8236-xx-03 H8237-xx-03 H8237-xxx
Bestellnummer	2TMA200050W0007, 2TMA200050B0005 2TMA200050W0010, 2TMA200050B0008 2CKA006136A0203, 2CKA006136A0204 2CKA006136A0205, 2CKA006136A0206 2TMA130051W0004, 2TMA130051B0004, 2TMA130051W0005, 2TMA130051B0005, 2TMA130051W0002, 2TMA130051B0002, 2TMA130051W0003, 2TMA130051B0003, 2TMA130050W0054, 2TMA130050B0054, 2TMA130050W0055, 2TMA130050B0055 2TMA130050W0058, 2TMA130050B0058, 2TMA130050W0060, 2TMA130050B0060 2TMA130050W0063, 2TMA130050B0063, 2TMA130050W0064, 2TMA130050B0064, 2TMA130051W0006, 2TMA130051B0006, 2TMA130051W0007, 2TMA130051B0007, 2TMA130050W0065, 2TMA130050B0065, 2TMA130050W0067, 2TMA130050B0067 2TMA130050W0066, 2TMA130050B0066, 2TMA130050W0068, 2TMA130050B0068 2TMA130050B0066, 2TMA130050W0066, 2TMA130050B0068, 2TMA130050W0068
Aktuelle Version	28.05.2021 DCA "Reparatur" -Taste

Aktueller Status:

DCA
ABB Touch DCA Download
BJE Touch DCA Download

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

GERÄTEKONFIGURATIONSAPP (DCA)

Version	Erscheinungsdatum	Updates und Release Notes
1.1.16.0	05/2021	Erweitert die Dinge, die repariert werden können, wenn die Reparaturschaltfläche aktiviert wird.
1.1.14.0	04/2021	Neue Schaltfläche "Reparieren" und Bugfixes
1.1.10.0	02.2021	Bugfix in diesem automatischen Fehlerbehebungsprozess
1.1.7.0	02.2021	Automatische Fehlerbehebung bei Problemen beim Kopieren oder Löschen
1.1.1 (Build 4)	11.2020	Die IP Touch Panels wurden hinzugefügt
1.1.1 (Build 1)	09.2020	Markteinführung