



BUILDING AND HOME AUTOMATION SOLUTIONS

# Release Note

## Tenton®

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

Busch-Jaeger Elektro GmbH  
Freisenbergstraße 2  
58513 Lüdenscheid, Germany  
Phone: +49 (0)2351 956 1600  
Email: [info.bje@de.abb.com](mailto:info.bje@de.abb.com)  
[www.busch-jaeger.de](http://www.busch-jaeger.de)

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

# Release Note

## ABB Tenton®

Product name	8gang control element 12gang control element
Product type	SB/U8.0.11, SB/U8.0.1 SB/U12.0.11, SB/U12.0.1
Order code	2CKA006330A0013, 2CKA006330A0014, 2CKA006330A0069, 2CKA006330A0070, 2CKA006330A0071, 2CKA006330A0072, 2CKA006330A0073, 2CKA006330A0074 2CKA006330A0015, 2CKA006330A0016, 2CKA006330A0075, 2CKA006330A0076, 2CKA006330A0077, 2CKA006330A0078, 2CKA006330A0079, 2CKA006330A0080
Latest change	ETS application version 1.4, Firmware version 0.1.14

Current Status:

Product Type	Order Code	Website	ETS Application	Firmware
SB/U8.0.11 SB/U8.0.1	2CKA006330A0013 2CKA006330A0014 2CKA006330A0069 2CKA006330A0070 2CKA006330A0071 2CKA006330A0072 2CKA006330A0073 2CKA006330A0074	<a href="#">Link</a>	V1.4 8gang control element /1.4 <a href="#">Download here</a>	V0.1.14 Please use ETS App „ABB Firmware Update 2.0”
SB/U12.0.11 SB/U12.0.1	2CKA006330A0015 2CKA006330A0016 2CKA006330A0075 2CKA006330A0076 2CKA006330A0077 2CKA006330A0078 2CKA006330A0079 2CKA006330A0080	<a href="#">Link</a>	V1.4 12gang control element /1.4 <a href="#">Download here</a>	V0.1.14 Please use ETS App „ABB Firmware Update 2.0”



**NOTE:**

We recommend ensuring that devices are always installed and operated using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

ETS APPLICATION

Product Type	Version	Release Date	Updates and Release Notes
SB/U8.0.11 SB/U8.0.1 SB/U12.0.11 SB/U12.0.1	1.4	01/2022	ETS App „ABB/BJE Update Copy Convert“ supports Tenton devices now. Function 1-button blind, Cycle time of telegram repetition fixed. Telegrams were not sent cyclically.
	1.3	- / -	Not published
	1.2	- / -	Not published
	1.1	- / -	Not published
	1.0	- / -	Market introduction

FIRMWARE

Note: For firmware update please use ETS App „ABB Firmware Update 2.0“ ([Engineering Guide](#))

Product Type	Version	Release Date	Updates and Release Notes
SB/U8.0.11 SB/U8.0.1 SB/U12.0.11 SB/U12.0.1	0.1.14	09/2021	Internal product improvements
	0.1.13	10/2020	Function „1 button operating mode, ‘Adjust thermostat settings’“ fixed.
	0.1.12	09/2020	Changes not related to these products.
	0.1.11	06/2020	Changes not related to these products.
	0.1.10	09/2019	Changes not related to these products.
	0.1.9	04/2019	Market introduction

HAUS- UND GEBÄUDEAUTOMATION

# Softwareinformation

## Busch-Tenton®

Produktname	8-fach Bedienelement 12-fach Bedienelement
Produkttyp	SB/U8.0.11, SB/U8.0.1 SB/U12.0.11, SB/U12.0.1
Bestellnummer	2CKA006330A0013, 2CKA006330A0014, 2CKA006330A0069, 2CKA006330A0070, 2CKA006330A0071, 2CKA006330A0072, 2CKA006330A0073, 2CKA006330A0074 2CKA006330A0015, 2CKA006330A0016, 2CKA006330A0075, 2CKA006330A0076, 2CKA006330A0077, 2CKA006330A0078, 2CKA006330A0079, 2CKA006330A0080
Aktuelle Version	ETS-Applikation Version 1.4, Firmware Version 0.1.14

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	ETS Applikation	Firmware
SB/U8.0.11 SB/U8.0.1	2CKA006330A0013 2CKA006330A0014 2CKA006330A0069 2CKA006330A0070 2CKA006330A0071 2CKA006330A0072 2CKA006330A0073 2CKA006330A0074	<a href="#">Link</a>	V1.2 HVAC/CO2-Gerät 6fach BE/1.2 <a href="#">Download hier</a>	V0.1.14 Bitte nutze die ETS App „BJE Firmware Update 2.0“
SB/U12.0.11 SB/U12.0.1	2CKA006330A0015 2CKA006330A0016 2CKA006330A0075 2CKA006330A0076 2CKA006330A0077 2CKA006330A0078 2CKA006330A0079 2CKA006330A0080	<a href="#">Link</a>	V1.2 HVAC/CO2-Gerät 10fach BE/1.2 <a href="#">Download hier</a>	V0.1.14 Bitte nutze die ETS App „BJE Firmware Update 2.0“



**BEMERKUNG:**

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

ETS APPLIKATION

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
SB/U8.0.11 SB/U8.0.1 SB/U12.0.11 SB/U12.0.1	1.2	01/2022	Die ETS App „ABB/BJE Update Copy Convert“ unterstützt jetzt auch die Tenton-Geräteserie.  Funktion 1-Tasten Jalousie, zyklische Wiederholung der Step-Telegramme gefixt. Das zyklische Senden wurde nicht ausgeführt.
	1.3	- / -	Nicht veröffentlicht
	1.2	- / -	Nicht veröffentlicht
	1.1	- / -	Nicht veröffentlicht
	1.0	04/2019	Markteinführung

FIRMWARE

Hinweis: Für Firmwareupdates verwenden Sie bitte die ETS App „BJE Firmware Update 2.0“ ([Engineering Guide](#))

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
SB/U8.0.11 SB/U8.0.1 SB/U12.0.11 SB/U12.0.1	0.1.14	09/2021	Interne Produktverbesserungen
	0.1.13	10/2020	Funktion „1-Tasten-Betriebsart 'RTR einstellen““ gefixt. Sie war ohne Funktion.
	0.1.12	09/2020	Verbesserungen für andere Gerätevarianten
	0.1.11	06/2020	Verbesserungen für andere Gerätevarianten
	0.1.10	09/2019	Verbesserungen für andere Gerätevarianten
	0.1.9	04/2019	Markteinführung