



BUILDING AND HOME AUTOMATION SOLUTIONS

# Release Note

## Busch-SmartTouch®

[English](#)

[Deutsch](#)

ABB STOTZ-KONTAKT GmbH  
Eppelheimer Straße 82  
69123 Heidelberg, Germany  
Telefon: +49 (0)6221 701 607  
Telefax: +49 (0)6221 701 724  
E-Mail: [info.bje@de.abb.com](mailto:info.bje@de.abb.com)  
[www.abb.com/knx](http://www.abb.com/knx)

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

# Release Note

## Busch-SmartTouch®

Product name Busch-SmartTouch® 7", 480-fold, FM

Product type 6136/07-8xx(-500)

Order code 2CKA006136A0203, 2CKA006136A0204  
2CKA006136A0205, 2CKA006136A0206

Latest change Firmware 2.14, 02/10/2021

Current Status:

Product type	Order code	Website	ETS Application	Firmware	DCA / PowerTool
6136/07-811	2CKA006136A0203	<a href="#">Link</a>	DCA V3.2 <a href="#">Download</a>	2.14 <a href="#">Download</a>	ABB Touch DCA <a href="#">Download</a>
6136/07-825	2CKA006136A0204	<a href="#">Link</a>	DCA V3.2 <a href="#">Download</a>		Release note <a href="#">Download</a>
6136/07-811-500	2CKA006136A0205	<a href="#">Link</a>	DCA V3.2 <a href="#">Download</a>		BJE Touch DCA <a href="#">Download</a>
6136/07-825-500	2CKA006136A0206	<a href="#">Link</a>	DCA V3.2 <a href="#">Download</a>		Release note <a href="#">Download</a>

NOTE:

We recommend to ensure that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up-to-date will to be accepted.

ETS APPLICATION

Product Type	Version	Since	Updates and Release Notes
6136/07-8xx(500)	3.2	11/2020	New DCA Application
	4.0	06/2017	Market Introduction with PowerTool



#### FIRMWARE

Product Type	Version	Since	Updates and Release Notes
6136/07-8xx(500)	2.14	10/2021	<ul style="list-style-type: none"><li>• Due to lack of components on the world market, we have to use other components and these have resulted in a software change.</li></ul>
	2.12	02/2021	<ul style="list-style-type: none"><li>• Solves the problem with WW/CW control</li><li>• Change the sending behaviour of the Fan control element</li></ul>
	2.11	09/2020	<ul style="list-style-type: none"><li>• Solves the problem of system clock deviation after long use.</li><li>• Solves the problem of KNX communication error after a short interruption of the KNX power supply (about 200 ms).</li></ul>
	2.07	06/2019	<ul style="list-style-type: none"><li>• Now all data points that are set with the "read on init" flag are read during the boot up.</li><li>• If an abnormal temperature is received, value "-" is now shown in the display.</li></ul>
	2.05	02/2019	<ul style="list-style-type: none"><li>• The problems with the Astro function have been rectified</li><li>• The problem with the automatic snapshot function when the external camera module is connected has been rectified</li><li>• Various status indications for control elements have been improved</li><li>• The sensitivity of a push-button was adjusted</li></ul>
	2.02	10/2017	<ul style="list-style-type: none"><li>• Password protection for time programs now also works in edit mode.</li></ul>
	2.00	04/2017	Market introduction

For firmware update please use Micro SD Card (FAT 32 formatted)

#### DEVICE CONFIGURATION APP

Product Type	Version	Since	Updates and Release Notes
6136/07-8xx(500)	1.1.16.0	05/2021	ABB Touch DCA <a href="#">Download</a>  Release note <a href="#">Download</a>

HAUS- UND GEBÄUDEAUTOMATION

# Softwareinformation

## Busch-SmartTouch®

Produktname	Busch-SmartTouch® 7", 480-fach, UP
Produkttyp	6136/07-8xx(-500)
Bestellnummer	2CKA006136A0203, 2CKA006136A0204 2CKA006136A0205, 2CKA006136A0206
Letzte Änderung	Firmware 2.14 Update, 02/10/2021

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	ETS Applikation	Firmware	DCA / PowerTool
6136/07-811	2CKA006136A0203	<a href="#">Link</a>	DCA V3.2 <a href="#">Download</a>	2.14 <a href="#">Download</a>	ABB Touch DCA <a href="#">Download</a>
6136/07-825	2CKA006136A0204	<a href="#">Link</a>	DCA V3.2 <a href="#">Download</a>		Softwareinformation <a href="#">Download</a>
6136/07-811-500	2CKA006136A0205	<a href="#">Link</a>	DCA V3.2 <a href="#">Download</a>		BJE Touch DCA <a href="#">Download</a>
6136/07-825-500	2CKA006136A0206	<a href="#">Link</a>	DCA V3.2 <a href="#">Download</a>		Softwareinformation <a href="#">Download</a>

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

ETS APPLIKATION

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
6136/07-8xx(500)	3.2	11/2020	Neue DCA Applikation
	4.0	06/2017	Markteinführung

FIRMWARE

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
6136/07-8xx(500)	2.14	10/2021	<ul style="list-style-type: none"> <li>Aufgrund fehlender Komponenten auf dem Weltmarkt müssen wir auf andere Komponenten zurückgreifen und diese haben zu einer Softwareänderung geführt.</li> </ul>
	2.12	02/2021	<ul style="list-style-type: none"> <li>Behebt das Problem mit der WW/KW-Bedienelement</li> <li>Änderung Sendeverhalten des Lüfterbedienelements</li> </ul>
	2.11	09/2020	<ul style="list-style-type: none"> <li>Behebt das Problem der Abweichung der Systemuhr nach längerem Gebrauch.</li> <li>Behebt das Problem des KNX-Kommunikationsfehlers nach einer kurzen Unterbrechung des KNX-Stromversorgung (ca. 200 ms).</li> </ul>
	2.07	06/2019	<ul style="list-style-type: none"> <li>Jetzt werden alle Datenpunkte, welche mit dem "read on init"-Flag gesetzt sind, beim Booten gelesen.</li> <li>Wenn eine abnormale Temperatur empfangen wird, wird jetzt der Wert "---" im Display angezeigt.</li> </ul>
	2.05	02/2019	<ul style="list-style-type: none"> <li>Probleme mit der Astro-Funktion wurden behoben</li> <li>Problem mit der automatischen Schnappschussfunktion bei angeschlossenem externen Kameramodul wurde behoben</li> <li>Verschiedene Statusanzeigen bei Bedienelementen wurden verbessert</li> <li>Empfindlichkeit eines Tasters wurde angepasst</li> </ul>
	2.02	10/2017	<ul style="list-style-type: none"> <li>Passwortschutz für Zeitprogramme funktioniert jetzt auch im Editiermodus.</li> </ul>
	2.00	04/2017	Markteinführung

Für Firmwareupdate verwenden Sie bitte eine Micro SD-Karte (FAT32-formatiert)

GERÄTEKONFIGURATIONSAPP (DCA)

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
6136/07-8xx(500)	1.1.16.0	05/2021	<p>BJE Touch DCA  <a href="#">Download</a></p> <p>Softwareinformation  <a href="#">Download</a></p>